

# 1990-91 Civic 3dr-4dr Main Menu

General Info



Suspension



Specifications



Brakes




Maintenance




Body



Engine




Heating, Ventilation  
and Air Conditioning



Cooling




Body Electrical



Fuel and Emissions



Engine Electrical



\* Transaxle







Steering



# Body Specifications

Hatchback



Unit: mm (in.)





3-14

Bumper Protrudes Away From Body



Sedan

Unit: mm (in.)



Bumper Protrudes Away From Body

# Front Bumper

## Replacement

*Bumper Protrudes Away From Body*

1. Remove the right and left front turn signal lights.
2. Remove the 2 bumper mounting screws on each side at the corner edge of the bumper.
3. Remove the 2 lower bumper mounting bolts and the 4 bumper mounting bolts.
4. Lift and remove the bumper by sliding it forward.

If necessary:

5. Remove the bumper brackets by removing the bracket mounting bolts.
6. Remove the screws, then remove the corner slide and slide clip.
7. Installation sequence is essentially the reverse order of removal.

NOTE: When installing a new bumper on a car with A/C, cut off and discard the 5 radiator grille covers.

**BUMPER BRACKET  
MOUNTING BOLTS**  
22 N·m (2.2 kg-m, 16 lb-ft)

**BUMPER MOUNTING BOLTS**  
22 N·m (2.2 kg-m, 16 lb-ft)

**FRONT TURN  
SIGNAL LIGHT**

**FRONT BUMPER**

**LOWER BUMPER  
MOUNTING BOLTS**

**FRONT SPOILER**  
Remove the mounting bolts,  
then remove the front spoiler.

**BUMPER BRACKET**

**BUMPER BEAM  
HOOK**

**BUMPER MOUNTING  
SCREWS**

**SPOILER MOUNTING BOLT**

**CORNER SLIDE CLIP**

**CORNER SLIDE**

**BUMPER**

**RADIATOR GRILLE  
COVERS**

○: CUT POINT



Photo taken at Mark's Auto Service  
(949) 689-5682  
1081 Camelback St.



1991 Honda Civic  
2 Door Hatchback

Bumper protrudes a significant distance  
away from body of Honda Civic

1991 Honda Civic  
2 Door Hatchback



Photo taken at Mark's Auto Service  
(949) 689-5682  
1081 Camelback St.

Bumper protrudes a significant distance  
away from body of Honda Civic