

YOUNKER MITSUBISHI

3820 E. Valley Rd.
 Renton, WA 98057
 (425) 251-8102 · Fax: (425) 282-0977
 www.youkermitsubishi.com

11:31

NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS.
 OTHER RETURNS FOR CREDIT MUST BE ACCOMPANIED BY THIS INVOICE IN THEIR ORIGINAL PACKAGING AND ARE SUBJECT TO A 20% HANDLING CHARGE. NO RETURNS ACCEPTED AFTER 7 DAYS. PURCHASE MADE BY CHECK REFUNDED AFTER CHECK CLEARS.
THANK YOU!
 ALL DAMAGED MERCHANDISE MUST BE REPORTED TO YOUNKER MITSUBISHI WITHIN 24 HOURS OF DELIVERY. YOUNKER MITSUBISHI CANNOT BE HELD RESPONSIBLE FOR DAMAGED MERCHANDISE AFTER 24 HOURS FOLLOWING DELIVERY.
EXCLUSION OF WARRANTIES: Any warranties on the parts and accessories sold hereby are those made by the manufacturer. The undersigned purchaser understands and agrees that YOUNKER MITSUBISHI makes no warranties of any kind, express or implied, and disclaims all warranties including warranties of merchantability or fitness for a particular purpose, with regard to the parts and/or accessories purchased and that in no event shall YOUNKER MITSUBISHI be held liable for incidental or consequential damage or commercial loss arising out of such purchase. The undersigned purchaser further agrees that the warranties excluded by YOUNKER MITSUBISHI include, but are not limited to any warranties that such parts and/or accessories are of merchantable quality or that they will enable any vehicle or any of its systems to perform with reasonable safety, efficiency or comfort.

DATE ENTERED 11 AUG 11	YOUR ORDER NO.	DATE SHIPPED 11 AUG 11	INVOICE DATE	INVOICE NUMBER 8944
---------------------------	----------------	---------------------------	--------------	------------------------

S
O
L
D
T
O

ACCOUNT NO. 11000
 MICHAEL
 425-965-8579

S
H
I
P
T
O

PAGE 1 OF 1

SHIP VIA		SLSM.	B/L NO.	TERMS	F.O.B.		
		1397		MC/VISA	RENTON, WA		
ORD.	SHIP	B.O.	PART NUMBER	DESCRIPTION	LIST	NET	AMOUNT
1	1	SP	6512A163YB	PANEL, AIR	227.63	210.77	210.77
1	1	SP	6512A164YB	PANEL, AIR	227.63	210.77	210.77
The following parts have been special ordered:							
		1	6512A163YB	PANEL, AIR			
		1	6512A164YB	PANEL, AIR			
<p><i>2 Front Bumpers</i> <i>Poto Glow Orange</i></p>							
<p>PAID AUG 11 2011 CA #2144</p>							
<p>(BB)</p>							
RETURN POLICY: NO RETURN OF SPECIAL ORDERS, ELECTRICAL OR EFI UNITS. INVOICE & ORIGINAL PACKAGE REQUIRED. UP TO 20% HANDLING CHARGE ON RETURNS. NO RETURN AFTER 14 DAYS OF INV. DATE.				PARTS		421.54	
				SUBLET			
				FREIGHT		0.00	
				SALES TAX		40.05	
				TOTAL		\$461.59	

CUSTOMER COPY

F R O N T I E R B A N K

MICHAEL S LAHAM OR
ELANA LAHAM
PO BOX 66
RENTON, WA 98057

2144

98-762/1251

15 AUGUST 2011

DATE

PAY TO THE
ORDER OF

YOUNKER MITSUBISHI

\$ 461⁵⁹/₁₀₀ XXXX

Only Four-hundred sixty-one and 59/100

DOLLARS



Security
Features
Details on
Back



FRONTIER BANK

www.frontierbank.com
(888) 779-4801

FOR 2 FRONT BUMPER PARTS FOR 2010 LANCER

⑆ 125107626⑆ 6411⑆ 002618⑆ 2144

Hardand Clarke

VOID VOID VOID VOID VOID VOID VOID

DATE 02025540 TIME
08/11/2011 001 11:32:21am
YOUNKER MITSUBISHI
3820 E VALLEY HWY
RENTON, WA 98057
425-251-8100

When you provide a check as payment you authorize us to use information from your check to process a one-time Electronic Funds Transfer (EFT) or draft drawn from your account, or to process the payment as a check transaction. You also authorize us to process credit adjustments, if applicable. If your payment is returned unpaid, you authorize us to collect your payment and the Return Fee amount below by EFT(s) or draft(s) from your account.

ELECTRONIC CHECK

SALE AMT \$461.59

RETURN FEE AMT \$30.00

Above fee increases to \$70.00 + 12% interest if unpaid after 33 days notice.

TRANS # 001 BATCH # 013
TRACE # 140031000000577355046
CHECK # 2144 APP CODE 3121

QUESTIONS? CALL 1-800-697-9263

- Secure**
- The patented "Security Weave" pattern on the back designed to deter check fraud (U.S. Patent No. 5,816,199)
 - Microprint (MP) lines printed on front and back
 - The words "ORIGINAL DOCUMENT" clearly appear across the back
 - Padlock icon visible on front and back
- Do not cash if:**
- Any of the features listed above are missing or appear altered
 - Fugitive ink on back looks pink or has disappeared
 - Brown stains and colored spots appear on both front and back
 - The word "VOID" appears clearly to the right of this message

 Padlock design is a certification mark of Check Payment Systems Association

Collision Specialists

303 Washington Ave N., Kent, WA 98032
 Email: Cspecialists2@qwestoffice.net

Damage Assessed By: DAVE NELSON

Deductible: UNKNOWN

Insured: mike laham
 Telephone: Home Phone: (425) 965-8579

Mitchell Service: 911311

Description: 2011 Mitsubishi Lancer Sportback GTS
 Body Style: 4D Wgn Drive Train: 2.4L Inj 4 Cyl AT FWD
 OEM/ALT: O Search Code: None
 Options: POWER LOCK, POWER WINDOW, POWER STEERING, CRUISE CONTROL, TILT STEERING COLUMN
 ANTI-LOCK BRAKE SYS., TRACTION CONTROL, ALUM/ALLOY WHEELS, AUXILIARY INPUT
 LEATHER STEERING WHEEL, FRONT AIR DAM, TINTED GLASS, AUTO AIR CONDITION
 TRIP COMPUTER, ANTI-THEFT SYSTEM, AUTOMATIC HEADLIGHTS
 AM/FM STEREO CD/MP3 PLAYER, ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS
 INTERIOR AIR FILTER, KEYLESS ENTRY SYSTEM, POWER DISC BRAKES, REAR SPOILER
 REAR WINDOW WIPER, STEERING WHEEL AUDIO CONTROLS

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type	Dollar Amount	Labor Units
1	101450	BDY	REMOVE/INSTALL	Frnt Bumper Cover			1.4 #

- Labor Note Applies

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	1.4	48.00	0.00	0.00	67.20 T	Total Replacement Parts Amount	0.00
Taxable Labor					67.20		
Labor Tax			@ 9.500 %		6.38		
Labor Summary	1.4				73.58		
III. Additional Costs					Amount	IV. Adjustments	Amount
Total Additional Costs					0.00	Customer Responsibility	0.00

ESTIMATE RECALL NUMBER: 09/20/2011 17:12:30 12293

Mitchell Data Version: OEM: AUG_11_V

UltraMate is a Trademark of Mitchell International
 Copyright (C) 1994 - 2011 Mitchell International
 All Rights Reserved

UltraMate Version: 7.0.433

Date: 9/20/2011 05:12 PM
Estimate ID: 12293
Estimate Version: 0
Preliminary
Profile ID: WALK IN

I.	Total Labor:	73.58
II.	Total Replacement Parts:	0.00
III.	Total Additional Costs:	0.00
	Gross Total:	73.58
IV.	Total Adjustments:	0.00
	Net Total:	73.58

* (0.00)
(73.58)

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.

Paid
[Signature]

PIF \$73.58 #104 9/20/11

Polish & WAX every 6 MOS \$65.00



Collision Specialists

HRS 8-530
M-F

Andrew McKellips
303 Washington Ave N
Kent, WA 98032

P 253.520.5553
F 253.520.5554
Toll Free 1.877.520.5553

Cspecialists2@qwestoffice.net

DDA Debits - 9/29/2011 - 2011905326 - 104 - \$73.58

ELANA LAHAM
P O BOX 66
RENTON, WA 98057

104
98-670/1251

9/20/11

Due

Pay to the order of Collision Specialists

\$73.58 XXXX ✓

Seventy three and 58/100 only

Debit

Security Features Details on back

VB Valley Bank

24-Hour Customer Service
Call (800) 448-2490 or from
Puyallup/Tacoma (253) 770-3548

*INSTALL 2 AIR BAGS ON FRONT BUMPER
FOR 2011 MITSUBISHI LANCER*

⑆ 1251067081 2011 ⑆ 905326 ⑆ 0104

DDA Debits - 9/29/2011 - 2011905326 - 104 - \$73.58

PAY TO THE ORDER OF
HERITAGE BANK
TACOMA, WA 98402-4374
⑆ 9251 ⑆ 354
FOR DEPOSIT ONLY
COLLISION SPECIALISTS INC.
12050 ⑆ 2756