
Transmission Log

The Boeing	Company	•		Monday	, 2008-	09-08 05:28	42	59658590
Date	Time	Туре	Job #	Length	Speed	Station Name/Number	Pgs	Status
2008-09-08	05:28	SCAN	01589	0:27	14400	94252718754		OK V.17 BM31



Transmission Log

The Boeing	Company			Friday	, 2008-	09-12 06:28	42	59658590
Date	Time	Туре	Job #	Length	Speed	Station Name/Number	Pgs	Status
2008-09-12	06:27	SCAN	01635	0:35	14400	94252718754	1	OK V.17 BM31

FAC	SIMILE
DATE:	Friday, 12 September 2008
SEND TO:	Newport Crossing Apartments 7311 Coal Creek Parkway SE Newcastle, WA 98059 Phone: 425 / 228-7368 FAX: 425 / 271-8754
FROM:	Michael and Elana Laham 7311 Coal Creek Parkway SE #E-304 Newcastle, WA 98059
SUBJECT:	FIX THE SURROUND OF THE BATHRUB/SHOWER ENCLOSURE AND THE BATHROOM CABINET UNDER THE BATHROOM SINK IN UNIT E-304.
To the st	aff of Newport Crossing Apartments:
supposed newly ren However, September enclosure unfinishe	your Leasing Agent Jennifer Engel on August 24, 2008, our , Unit E-304, that we moved into on September 1, 2008 is to be "fully and newly renovated". We are paying the fully novated RENT price. on the day that we moved into our apartment, E-304, which was 1, 2008, we found that the "surround" of the bathtub/shower - the walls surrounding the bathtub - in the bathroom is ed and has paint chipping off of its walls. Therefore, we
was Septe in our ba	on, on the day that we moved into our apartment, E-304, which ember 1, 2008, we found that the paint under the bathroom sink throom cabinet is peeling away. Therefore, we need your nee personnel to fix it.
was Septe in our ba maintenar Now that your cont the walls underneat 6:00 PM.	mber 1, 2008, we found that the paint under the bathroom sink athroom cabinet is peeling away. Therefore, we need your
was Septe in our ba maintenar Now that your cont the walls underneat 6:00 PM. maintenar	ember 1, 2008, we found that the paint under the bathroom sink throom cabinet is peeling away. Therefore, we need your nee personnel to fix it. we have completely moved in, we are home and available to let tractors and maintenance personnel into the bathroom to repair s of the bathrub/shower "surround" and the bathroom cabinet th the bathroom sink, Monday through Sunday from 9:00 AM to No need to contact us. Just send your contractors and nee personnel over to our apartment E-304. Viz/2008
was Septe in our ba maintenar Now that your cont the walls underneat 6:00 PM. maintenar Sincerely	ember 1, 2008, we found that the paint under the bathroom sink throom cabinet is peeling away. Therefore, we need your nee personnel to fix it. we have completely moved in, we are home and available to let tractors and maintenance personnel into the bathroom to repair s of the bathrub/shower "surround" and the bathroom cabinet th the bathroom sink, Monday through Sunday from 9:00 AM to No need to contact us. Just send your contractors and nee personnel over to our apartment E-304. Viz/2008